

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
5958	5/05/10	High Street, from the roundabout to Staples Street	Power poles on western side need repainting for the first 2 metres height. Reflector discs also needed on these poles to improve safety.		Forwarded to Selwyn Steadman for a decision		DO
7528	22/06/10	Wallace Street	Street signs along Wallace Street between High and Wilkinson Street need to be inspected. Some have been pushed around, some are bent and the car park one has been removed.		Inspection taking place by Downers 30/07/10 and should be completed within week	2/08/10	DO
37878	1/07/10	Woodlands Drain	Drain needs cleaning up. There is a lot of weed growth in the drain as well as plastic and paper litter		assigned to contractor 2/07/10	2/08/10	DO
37976	14/07/10	Pathway from Motueka Memorial Hall to Poole Street, Motu	Pathway needs more lighting, particularly near tennis club. This has become a hang out spot and there is now regular vandalism occurring. The senior citizens have also had vandalism occur. The pathway also needs to be lifted up outside the tennis clubrooms because as soon as it rains the path is then under water.		Kathy Tohill to look into		DO
37977	14/07/10	Motueka Tennis Club, Pah Street Motueka	Trees at the back of the tennis courts need trimming		Order printed 21/07/10		DO
38157	14/07/10	Pah Street, Motueka	Road surface broken away from beside the manhole adjacent to the pedestrian crossing by the Memorial Hall		Assigned to contractor 02/08/10		DO
9123	4/08/10	Lodder Lane	Roadside open drains need to be cleared of weeds. Some sections are reasonably clean, but mostly there is a heavy weed growth inhibiting stormwater flow towards the estuary.		TDC do not maintain land drains but the water table area is due to be completed by beginning September		DO

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
38190	4/08/10	Memorial Park, Pah Street, Motueka	Mr Ogilvie would like a rubbish/recycling bin installed by the library, possibly attached to the power pole in the grassed area at the south-western corner of the library.				DO
38225	9/08/10	109 Old Wharf Road	Stormwater floodgate is jacked open and allowing seawater to flow into neighbouring properties. Needs attention.		order printed 03/08/10		DO
38248	11/08/10	Glenaven Drive, Motueka	Retention ponds in Glenaven Drive do not drain properly after heavy rain. The drain is higher than the surrounding land and the land needs raising up to the same level to enable the water to disappear.		passed to contractor 11/08/10		DO
38249	11/08/10	Pah Street, Motueka	Wooden tree protector, surrounding tree just west of the Motueka Library has been damaged and is wobbly. Needs repairing		order printed 13/08/10		TF