Complaints again pour in over High St North flooding

The ongoing flooding issues along High Street North have continued after the recent heavy rains.

The problem has reared its head ever since construction on this section of road earlier this year. The drainage system does not lead to any outlet.

Two major pools were causing driving issues for south-bound traffic in s particular when the first downpours came toward the end of last week.

Unfortunately several drivers have been taking to the wrong side of the road to avoid the pools.



High St North in heavy rain: The large pools are one thing but many drivers are taking to the wrong side of the road to avoid them.