

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
31809	24/06/09	North Street	The heavy rain in June has undermined the work done in this street. The potholes need refilling. Long term solutions are needed for drainage and footpathing. Local residents would like meeting to discuss options. CB is happy to arrange.		Work to be progressed as timeframes allow. Steve communicated with David re this. Steve is happy to meet with residents if required and the meeting is organised by the Community Board.		DO
33329	21/07/09	Motueka memorial Hall/Library	The area of concrete between the hall and the library has been patched many times. It is uneven, particularly near the ramp by the Hall emergency doorway and has a mix of patched asphalt and cracked concrete. This area needs to be relaid		Project now with Fulton Hogan to reseal area	20/11/09	DO
952	27/08/09	Corner Trewavas Street & Everett Street	The new seal at this corner has not been properly applied and has lifted badly. (Contractor either Fulton Hogan or Concrete & Metals - He thinks FH). This is similar to the problem in Greenwood Street.		Waiting on FH to fix seal. Programmed for 17/18 December		DO
33213	10/09/09	Opposite 49 Motueka Quay	Large gum tree needs attention. Several broken and dead branches need attending to.		Kathy and Brad monitoring tree as there is some deterioration (6/11/09)		Beth Bryant via community board
2556	2/11/09	52 Tudor Street	Pothole needs repairing			3/11/09	DO
2558	2/11/09	Riwaka-Sandy Bay Road	South side of hill needs edges resealing, particularly on the bends		with contractor for inspection		DO
2559	2/11/09	Umukuri Road	road needs maintenance by approaches to Brooklyn School		Will be part of a road reconstruction. In the design process at present		DO
34104	2/11/09	North Street Reserve	Heavy plastic turnstyle equipment not working properly		Kathy Tohill checked equipment and appears to just need oiling (3/11/09)		DO
2768	23/11/09	Corner Wilkie Street and Jocelyn Ave	Street sign on the corner needs to be secured at the base		passed to contractor to action		DO

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
2769	23/11/09	Tudor Street	Chevron arrow outside number 40 is bent. May need replacing		passed to contractor to action		DO
2785	26/11/09	King Edward Street	There needs to be a sign in King Edward Street at the approach to High Street showing the distance and direction of the I-Site				DO