

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
5958	5/05/10	High Street, from the roundabout to Staples Street	Power poles on western side need repainting for the first 2 metres height. Reflector discs also needed on these poles to improve safety.		Forwarded to Selwyn Steadman for a decision		DO
37976	14/07/10	Pathway from Motueka Memorial Hall to Poole Street, Motu	Pathway needs more lighting, particularly near tennis club. This has become a hang out spot and there is now regular vandalism occurring. The senior citizens have also had vandalism occur. The pathway also needs to be lifted up outside the tennis clubrooms because as soon as it rains the path is then under water.		Kathy Tohill to look into		DO
37977	14/07/10	Motueka Tennis Club, Pah Street Motueka	Trees at the back of the tennis courts need trimming		Order printed 21/07/10	9/09/10	DO
38157	14/07/10	Pah Street, Motueka	Road surface broken away from beside the manhole adjacent to the pedestrian crossing by the Memorial Hall		Assigned to contractor 02/08/10	1/09/10	DO
38190	4/08/10	Memorial Park, Pah Street, Motueka	Mr Ogilvie would like a rubbish/recycling bin installed by the library, possibly attached to the power pole in the grassed area at the south-western corner of the library.		order printed 03/09/10		DO
38225	9/08/10	109 Old Wharf Road	Stormwater floodgate is jacked open and allowing seawater to flow into neighbouring properties. Needs attention.		order printed 03/08/10	30/08/10	DO
38248	11/08/10	Glenaven Drive, Motueka	Retention ponds in Glenaven Drive do not drain properly after heavy rain. The drain is higher than the surrounding land and the land needs raising up to the same level to enable the water to disappear.		passed to Gary Clark 14/09/10 to discuss with Kim Arnold as to possible solution		DO

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
38249	11/08/10	Pah Street, Motueka	Wooden tree protector, surrounding tree just west of the Motueka Library has been damaged and is wobbly. Needs repairing		order printed 13/08/10	9/09/10	TF
38558	7/09/10	Memorial Hall	Driveway on the eastern side of the Memorial Hall has some pot-holes in it		order printed 13/09/10		DO
9569	7/09/10	Motueka River West Bank Road	Series of potholes for about 150 metres heading south from 625 Motueka River West Bank Road			8/09/10	DO
9570	7/09/10	Cnr Tudor & Wilkinson Streets	Street sign needs concreting in place.			8/09/10	DO
9667	21/09/10	Riwaka-Sandy Bay Rd	Approximately 100 metres up the hill from the Riwaka side there is a series of potholes		Temporarily fixed, permanent fix to be done early November		DO
9668	21/09/10	Riwaka-Sandy Bay Rd	Approximately 1 km up the hill from the Riwaka side there is a dangerous bend with unusual camber. Even when driving slowly your vehicle gets pushed across centre line.		Reviewed by MWH and will be upgraded as required as part of their programme		DO
9670	21/09/10	Riwaka-Sandy Bay Rd	Approx 400 metre from summit on Marahau side there is a sharp bend. This needs a chevron sign and possibly a speed restriction.		as above		DO
9671	21/09/10	High Street, West Side	Between 460 & 472 High St there are at least 2 sections in the footpath where there is a variance of 3-5cm in the height.		Will be filled if the variances are over 10mm		DO
9787	28/09/10	52 Tudor Street	Pothole outside this address		Temporarily fixed, permanent fix to be programmed in	4/10/10	DO
9788	28/09/10	Walkway between Wilkinson and McCarthy Crescent	Walkway sign needs turning around			4/10/10	DO
10058	7/10/10	Woodland Ave	Road marking by 2 Woodland Ave needs redoing		No immediate action required. Will be done as part of remarking programme prior to Christmas		DO

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
10074	12/10/10	Primmer Lane	Service lane north side of fire station has potholes and needs seal repair. Also needs carparks marked out		Passed to contractor		DO
10076	12/10/10	Greenwood Street	Carpark behind Salvation Army. Lot 5 DP 1335, has potholes needing repairing. Also needs carparks marked out		Pothole repaired., carpark sprayed and swept. Marking to be considered by TDC		DO