SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
5958		High Street, from the roundabout to Staples Street		Painting not required as poles are behind kerb.	Forwarded to Selwyn Steadman for a decision		DO
37976	14/07/10	Pathway from Motueka Memorial Hall to Poole Street, Motu	Pathway needs more lighting, particularly near tennis club. This has become a hang out spot and there is now regular vandalism ocurring. The senior citizens have also had vandalism ocur. The pathway also needs to be lifted up outside the tennis clubrooms because as soon as it rains the path is then under water.		Kathy Tohill to look into		DO
38248	11/08/10	Glenaven Drive, Motueka	Retention ponds in Glenaven Drive do not drain properly after heavy rain. The drain is higher than the surrounding land and the land needs raising up to the same level to enable the water to disappear.	Detention area to be filled/ reshaped and regrassed in the autumn	passed to Gary Clark 14/09/10 to discuss with Kim Arnold as to possible solution		DO
38558	7/09/10	Memorial Hall	Driveway on the eastern side of the Memorial Hall has some pot-holes in it	Under action by Engineering	order printed 13/09/10		DO
9671	21/09/10	High Street, West Side	Between 460 & 472 High St there are at least 2 sections in the footpath where there is a variance of 3-5cm in the height.		Completed, only lips above 10mm can be practicall treated	26/12/10	DO
10058	7/10/10	Woodland Ave	Road marking by 2 Woodland Ave needs redoing		To be remarked as part of network remark, which is underway now		DO
10362	8/11/10	2A Greenwood Street	Carpark has a lot of weeds and litter in it. Mr Ogilvie would like this area marked with carparking spaces		Weeds and detritus have been cleared, pavement repairs have been programmed, which will be followed by pavement markings		DO

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
10434	10/11/10	Hickmott Place	No Parking" lines needed on the east side of Hickmott Place. If vehicles are parked on this side of the road any traffic coming from Tudor Street has to travel on the wrong side of the road to get past. There is a parking bya on the west side of this road.		report being prepared for council consideration		DO
39354	10/11/10	Old Wharf Road	Metal floodgates covered in algae and weed. Needs cleaning and painting.		referred to Downers for costing		PH
11438	20/12/10	52 Tudor Street	Sealing repairs required outside 52 Tudor Street. A temporary job was done some weeks ago. But the seal has deteriorated		Programmed and should be completed by end of April. Part of network repairs		DO
11439	20/12/10	Old Wharf Road	Sealing repairs required at the northern end of Old Wharf Road, east of Thorp Street		To be programmed and prioritised		DO
11441	20/12/10	Wilkie Street	Seal Repairs required on Wilkie Street, south of Parker Street intersection, to Fry Street		Crack seal to be completed during sealing season. le before April		DO
11442	20/12/10	Western side of High Street	Weed growth is bad in the kerb channels on the western side of High Street, south of Woodlands Ave intersection			15/01/11	DO
11443	20/12/10	High Street	Weed growth in the kerb channels is bad along the eastern side of High Street, north of Fearon Street			15/01/11	DO
11444	20/12/10	Old Wharf Road	The grass verge along Old Wharf Road, east of the Recreation Centre is being mowed, however an area near the open drain and fence line are being left. Can this be mowed as well as it looks untidy.		Passed to maintenance contractor to mow if within the road reserve		DO