

Action List

For September 2008 meeting

Issue	Action Taken	Result/Outcome
Delegated functions for the Community Boards	TDC to organise. (Mayor, CEO, Board, Managers)	TDC to initiate a meeting with the Boards (jointly) to progress the matter. (Carried over from July 2008).
Traffic survey for High Street South and Wildman Road	Steve Elkington to report	A "warrant" survey is being conducted and Steve Elkington to report once the survey is available. (Carried over from July 2008).
Public toilets at Port Motueka	Paul Hawkes	Waiting for plan and costings to be finalised.
Recycling – bins	Tara Forde	Letters to community groups – responses
Street lighting request in Wildman Road (High Street South and Hursthouse Street)	Survey letters distributed and survey responses	Satisfactory response. Report in August 2008 agenda sent to TDC.
Regional Cycling and Walking Review	Public meeting held 28 July 2008	Report in August 2008 agenda. Results to be sent to Opus and TDC. Draft expected in September.
Thorp's Bush planting programme (2008)	Request to Beryl Wilkes (Reserves Manager)	Some walkway clearing in Thorp's Bush. Kathy Tohill-Curnow to liaise with Board
Goodman Park soccer fields; open/closed sign, refuse bins	Request to parks and Reserves	Additional sign and rubbish bins to be located when available.
Flaxes and nuisance at tennis courts	Service request	Kathy Tohill-Curnow has been trying to contact Agnes McNabb without success (as at 01/09/08)
Thorp Street (opposite Pioneer Cemetery) near Fearon Street	Service request	Preparatory work in place. Wet weather probably slowing completion.
21 Whakarewa Street – Vegetation obstructing footpath	Service request	Fulton Hogan have spoken to the occupants and they appeared keen to trim the hedge themselves. Fulton Hogan will also monitor the property to see if they do trim the hedge. If it's not done by next Monday, Fulton Hogan will trim the hedge and advise Council that the residents need to be sent the bill.
Footpath/cycleway projects 2008-2009 and Public Consultation Motueka River Works	Engineering Services	No response

