

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
45760	16/04/12	Woodlands Canal, Motueka	The drain through Thorps Bush and the Woodlands canal to the Recreation centre needs to be cleared of weeds and grass growth		MWH and Downers meeting on site 29/05/12 to discuss		DO
2-20308	15/06/12	Walkway between Parker Street and Kitakita Grove	This walkway has weeds either side of the concrete strip that need to be removed/sprayed		Contractor to spray week 9-13 July		DO
2-20310	15/06/12	CBD Motueka	Liquor restriction signs painted on footpath need to be remarked.		No point in repainting at present as liquor bylaw is going to extend the area of ban in Motueka. Painting will then be done		DO
46420	15/06/12	Thorps Bush	Near to the walking bridge to Avalon Court a number of shrubs have been trimmed and branches thrown into Thorps Drain, partly blocking drain between 2 large culverts		With Kim Arnold for action		DO
46423	15/06/12	Whakarewa Street	Mr Ogilvie would like 2 more rubbish bins erected along Whakarewa Street, towards Manoy Street.		transferred to ramm ID20313. E-mailed Jeremy 28/06/12		DO
2-20507	27/06/12	Wilkinson St/Greenwood Street intersection	Pothole on the southeast corner needs to be repaired.		Temporary fix done 6 July. Permanent fix to be programmed		DO
2-20532	27/06/12	Tapu Bay - Stephens Bay area	There is a lot of leaf and tree litter in the roadside channel and road edges in this locality. The stormwater sumps are also clogged with detritus. These need sweeping/cleaning			6/07/12	DO
2-20533	27/06/12	Sandy Bay - Marahau Road	From Moss Road to the Abel Tasman National Park entrance the road signs need to be straightened and cleaned. Also some of the marker pegs are missing and need replacing		To be completed in July		DO

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
46562	27/06/12	Thorp Street, Greenwood Street corner	There is still a blockage of the stormwater drains/sumps at this corner (south eastern). Both the rain events this month have caused flooding across both streets.		With MWH. Inadequate system capacity, solution to be investigated and prioritised		DO
2-20550	27/06/12	Harry Rankin Street	Sign on the corner of Harry Rankin Street and Fearon Street is twisted and needs re-alignment		Sign straightened 2 July, waiting on new brackets to arrive to replace existing non standard brackets		DO
2-20551	27/06/12	Cnr High Street and Pah Street	Bollard on corner has been smashed into and damaged. This has damaged concrete path and surrounds as well		To be completed in July. Contractor pricing repair		DO