

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
4363	22/01/10	High Street South, Motueka	The footpath between the roundabout and Wildman Road needs improved maintenance. Weed growth both narrows the path and is an issue in the path. Mr Ogilvie suggests that given the residential nature of this street, a two-coat chip seal footpath would be an appropriate solution to the continuing costs of maintenance		sprayed edge of path, now waiting on vegetation to die. Programmed to finish		DO
36330	8/03/10	Trewavas Street Beach Reserve	There are 3 (or 4) walkways from Trewavas St to the Beach Reserve , they each need to be cleared and cleaned of overhanging shrubs/trees and made tidier for walkers, also the signs need to be uniform (one is blue the others are old yellow/black)		Passed to Sicon for tidying up. Will followup having both signs made standard in blue.		DO
1004610	31/03/10	College street	Complaint from Community board meeting. Vehicles turning into College Street from Queen Victoria Street build up speed thinking it is a 70km area. No signs indication speed limit.		There is one sign in College Street and they have no intentions of putting any more up. The speed limit in all the surrounding streets in 50kph so there would be not reason for people to assume it is 70kph. If cars are speeding it is a police issue		meeting
36903	14/04/10	I-Site, Wallace Street	Recycling bin in Wallace Street outside the i-site is frequently overflowing. Can this please be emptied more often.		Been included on Motueka collection run to be emptied. Looking into whether another pod is required		TF